

2.0s since last NuMI kicker fire - \$A9 signal
44.6s since last update of beam monitoring files
Last update at: Fri Jun 10 14:34:17 2005

WARNING: this window should NOT be used for estimating spill frequency!!!

This process monitors beam monitoring data files

It checks that beam monitoring data files are updating with each \$A9 signal

If files stop updating you will find further instructions here